

I'm human



Intel dual band wireless-ac 8265 bluetooth not working

I'm using the MSI Herald-AC Intel AC 8265 WiFi Card in my Windows device. To resolve the Bluetooth issue on my computer: First I went into Device Manager > Universal Serial Bus Controllers and noticed that there was a faulty USB device. I removed it. This should be fixed when you restart your computer. To fix this issue, simply turn off then back on your system and check if Bluetooth functions properly. In another case laptop user is having the same problem with HP notebook 15-af127nf with Windows10 64 bits, where wifi works fine but the bluetooth does not work after installing new wifi card Intel AC-8265. The user tried to install/reinstall drivers from Intel but it did not help and also tried adjusting bluetooth services settings in services.msc to no avail.

Intel dual band wireless ac 8265 bluetooth not working. Intel dual band wireless-ac 8265 driver not working. Intel wireless ac 8265 not working. Intel dual band wireless not working. Intel dual band wireless-ac 8265 not operational. Intel dual band wireless-ac 8265 not working. Intel dual band wireless-ac 8265 problems windows 10. Dual band wireless-ac 8265 driver.